

### Orton Cone Conversion Chart:

Cone	Temp	Range
10	2345	2381
9	2300	2336
8	2280	2320
7	2262	2295
6	2232	2269
5	2167	2205
4	2124	2161
3	2106	2138
2	2088	2127
1	2079	2109
01	2046	2080
02	2016	2052
03	1987	2019
04	1945	1971
05	1888	1911
06	1828	1855
07	1789	1809
08	1728	1753
09	1688	1706
010	1657	1679
011	1607	1641
012	1582	1620
013	1539	1582
014	1485	1540
015	1456	1504
016	1422	1465
017	1360	1405
018	1319	1353
019	1252	1283
020	1159	1180
021	1112	1143
022	1087	1094